Attorney Docket No. 1934.1001 (formerly 1687.1005)

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Hiroyuki YAMASHITA, et al.

Application No.: 10/766,955

**ATTENTION** 

Confirmation No.: 2505

CERTIFICATE OF CORRECTION

Filed: January 30, 2004

BRANCH

U.S. Patent No.: 7,155,690

Issued: December 26, 2006

A METHOD FOR CO-VERIFYING HARDWARE AND SOFTWARE FOR A

SEMICONDUCTOR DEVICE (As Amended)

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Registration No. 22,010

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

MAY 1 0 2007

TOTTOG!

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO: 7,155,690

DATED: December 26, 2006

INVENTOR(S): Hiroyuki YAMASHITA, et al.

Column 10, Line 38, change "teatbench" to --testbench--.

Column 11, Line 9, change "teatbench" to --testbench--.

Column 11, Line 11, change "teetbench" to --testbench--.

Column 11, Line 53, change "interruct" to --interrupt--.

Column 12, Line 16, change "The" to --the--.

Column 12, Line 41, change "end" to --and--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,155,690

No. of add'l copies @ 50¢ per page